

SERVICE TOOLS

Landrover EPB & Service Tool



Landrover EPB & SLR Tool

Resets Service Lights on Landrover and Range Rover Vehicles *

Supports Latest CAN Protocols

Simple Push Button Operation

Performs Park Brake Functions

Petrol and Diesel Vehicles

Fast Service Light Reset Process

Park Brake Un-Jam Function

* Discovery 3 & Range Rover Sport 05-09

Designed, Manufactured and Supported by SP Diagnostics in the UK

The new Landrover service tool has been designed not only to extinguish service indicators, but to provide electronic park brake functions such as releasing the park brake cable allowing the brakes to be changed.

Fast and efficient, the service light reset function takes seconds, where other manufacturers equipment can take 10s of minutes!

- Service Reset - Resets the service indicator on the vehicle
- EPB Release - Releases the cable to allow the brakes to be changed on the vehicle
- Cable Reset - Resets the cable after the emergency cable release has been activated
- EPB Unjam - Allows the EPB to be un-jammed when the vehicle has entered a state when brakes screech when applying the park brake, the rear brakes squeak or rub when the vehicle is moving or there is evidence of shoe-drag.
- Clear Codes - This allows you to clear any codes that are or have been present as a result of the emergency cable being activated or the park brake becoming jammed

Download a Full Application List from www.spsupport.com



Diagnostics

www.SPDiagnosics.com

SP Diagnostics - PO Box 3467 - Chippenham - Wiltshire - SN15 9FH
sales@spdiagnostics.com - 0845 601 6510